

Barr et al. Filed 10/3\_/2001
Method To Correct For
Malfunctioning Ink Ejection
Elements In A Single Pass Print
Mode Sheet 1 of 6 10014029-1




Barr et al. Filed 10/3\_/2001
Method To Correct For
Malfunctioning Ink Ejection
Elements In A Single Pass Print
Mode Sheet 2 of 6 10014029-1



The first time that the

The heat that the heat he

Barr et al. Filed 10/3\_/2001
Method To Correct For
Malfunctioning Ink Ejection
Elements In A Single Pass Print
Mode Sheet 4 of 6 10014029-1



F1G. 4




FIG. 6




FIG. 5